

## CHROMATIC TRANSFER SCALES, AATCC



### **AATCC 9 Step Chromatic Transference Scale**

#### **KCT- 3070**

The 9 Step Chromatic Transference Scale is used to visually evaluate color transfer of staining. The scale has 5 hues which are red, yellow, green, blue and purple which were all selected from the Munsell Book of Color. Evaluation Procedure 8 with instructions on how to use the scale is included